

Annexure D

BUILDING SAFETY CERTIFICATE

No. 0391/25

Dated: 15/05/2025

It is certified that the existing building SARDAR PATEL SCHOOL (name of the building or premises) at Ramedi Danda, Hamirpur (U.P.) (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	<u>2</u>	<u>2</u>				

The building is owned/occupied by Sardar Patel School, Hamirpur (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D. (Name of Department/ Govt.) on 13/05/2025 (date of inspection) in the presence of Mr. Govard Singh (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 15/05/25 for a period of 14/05/26 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 15/05/2025 at Hamirpur (U.P.) by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: [Signature]

Name: Mr. V.K. Singh

Designation: अधिशासी अभियन्ता

Name & Address of Department/ Office: सी० वि०, हमीरपुर

[Signature]
Principal
Sardar Patel School
Ramedi Danda, Hamirpur
Pin-210301

[Signature]
Manager,
Sardar Patel School,
Ramedi Danda, Hamirpur (U.P.)